


Map



- 1 management
- 2 purchasing department
- 3 human resources and legal department
- 4 finance & controlling
- 5 reduction plant
- 6 steel plant management
- 7 logistics & transport
- 8 canteen
- 9 technical services
- 10 work council & quality management
- 11 rolling mill management
- 12 depot
- 13 delivery of scrap metal
- 14 company HRV
- 15 company Linde

In case of emergency the alarm occurs via sirens!

- sidewalk
- Hazard duty (gathering) point
- Medical service
- Traffic area
- Road traffic regulations applies on site switch on low-beam lights

- Industrial area rail traffic has priority
- Attention! Fork lift traffic
- Attention! Transport of liquid slag

- Attention! Pedestrians crossing
- Only use marked/assigned parking areas

In all traffic areas:



ArcelorMittal

Safety rules

ArcelorMittal Hamburg GmbH

for contractors and visitors



ArcelorMittal Hamburg GmbH
Dradenausstraße 33
21129 Hamburg
Tel. +49 40 7408 - 0

Stand 10.2018

Our most important value is our employee´s health and safety! Our goal: zero accidents

Basic information

The complete plant of ArcelorMittal Hamburg GmbH underlies the special security rules of ISPS (International Ship and Port Facility Security Rules). The area is patrolled frequently and controlled by video cameras.

Safety at work

All contractors and visitors are engaged to comply with the instructions and rules of ArcelorMittal Hamburg GmbH. Instructions and other rules for health and safety must be considered exactly. The plant security agents (e.g. fire protection officer) and ArcelorMittal representatives instructions must be followed. The commissioned contractors must provide their employees the necessary personal protection equipment for their tasks. This includes PPE against falling from heights and gas detectors.

Instruction

Before beginning a task on premises of ArcelorMittal Hamburg GmbH a instruction must be done on the health and safety gateway ("Arbeitsschutzportal").

Link: <http://arbeitsschutzportal.arcelormittal.hamburg>

About special hazards, contractors get briefed in written form on-site at their workplace by the ArcelorMittal representative. Visitors get a visitor´s pass with the most important safety information.

You always must be able to show a valid safety certificate/partner company´s pass or a valid visitor´s pass.

Emergency numbers

Medical emergency:	+49 40 7408 - 333
Fire:	+49 40 7408 - 355
Plant security:	+49 40 7408 - 278

Risk assessment

For the planned tasks the contractors must evaluate, assess and document the hazards. For a safe work environment, appropriate actions must be determined. The risk assessment must be adapted to circumstances and conditions on the plant of ArcelorMittal Hamburg GmbH.

Safety signs

You can find signs on the complete plant, that are important for your safety. Consider these signs giving orders, prohibitions and warnings!

If necessary, please ask your AM-representative for more information.



No trespassing! Restricted access!



Smoking and fire forbidden!



Attention! Suspended loads!



Attention! Electromagnetic radiation!



Hazard duty (gathering) point

Electromagnetic fields

In certain areas electromagnetic fields may appear and have influence on active implants. Please contact the plant security if necessary.

Gas hazard areas

On the plant, there are some gas hazard areas. These areas are marked and may not be entered without additional safety precautions and registration.

Personal protection equipment

Basic PPE

- helmet
- safety shoes
- workwear



Additional PPE in certain areas

When entering the production halls and manufacturing plants, including the slag-, ore- and scrap area:

- safety glasses
- if marked: ear protection
- depending on the task: safety gloves

Inside the steel plant hall, rolling mill hall and reduction plant, while in operation

- fireproof clothing

At the quay facilities and traffic areas:

- hi visible clothes (vest)

For detailed information about the guidelines in the workshops, ask your representative!

Use of equipment

Technical equipment of ArcelorMittal Hamburg GmbH may not be used without permission. Furthermore, only tools/equipment that are safe to operate and certified, may be used. The deployed employees must be qualified and able.

Hazardous material and waste

Hazardous material and accruing waste must be announced to the representative of ArcelorMittal.

Scaffolds / Additional work permit

Scaffolds may only be entered if visibly approved (approval card for scaffolds). Scaffolds may only be changed by the scaffolder.

You will get additional work permits for

- hot works (inflammable operations/explosion hazards)
- operations in confined spaces
- operations with falling hazard

from your ArcelorMittal representative.